

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

Patented Oct 4, 1994

Fig. 1A




Fig. 1B




Fig. 1C




FIG. 2A




Fig. 2A




Fig. 2B




Fig. 2C

APPROVED	O.G. FIG.
BY	CLASS SUBC.
DRAFTSMAN	

104240" EST-4250

Fig. 3




FIG. 4

Fig. 4





Fig. 5



04240" 042401
054153" 042401

APPROVED	O.G. FIG.	
BY	CLASS	SUBJECT
DRAFTSMAN		




Fig. 6A




Fig. 6B



Fig. 6C




Fig. 6D




Fig. 6E




Fig. 6F





Fig. 6G

0044340-00000000

Fig. 7



05841537-042401

FIG. 9A

Fig. 9A




Fig. 9B





Fig. 9C



104240 EST 4250




FIG. 11

Fig. 11





Fig. 12



094153 0440 25914350

APPROVED	O.G. FIG.
BY	CLASS SUBC
DRAFTSMAN	




Fig. 13A




Fig. 13B cross sectional view of A1-A1'




Fig. 13C cross sectional veiw of A2-A2'

Fig. 14A




Fig. 14B





Fig. 14C



05041537 043401

FIG. 15A




Fig. 15B




Fig. 15C




Fig. 15D




FIG. 16A




Fig. 16B





Fig. 16C



APPROVED	O.G. FIG.
BY	CLASS SUBC
DRAFTSMAN	

T04240" / E5T4B50

Fig. 17




FIG. 18A




Fig. 18B




Fig. 18C





Fig. 18D



T04240" 266T4850

Fig. 19A




Fig. 19B




Fig. 19C




FIG. 20

Fig. 20




FIG. 21A




Fig. 21B




Fig. 21C




FIG. 22A




Fig. 22B




Fig. 22C




FIG. 25

Fig. 25





FIG. 26

Fig. 26






Fig. 27A




Fig. 27B




Fig. 27C




Fig. 27D




Fig. 27E




Fig. 27F

2001 2002 2003 2004 2101 2102 2103 2104 2105 2106 2201 2202 2203 2204 2205 2301 2302 2303 2401 2402 2403 2404 2405 2501 2502 2503 2504




Fig. 28A




Fig. 28B





Fig. 28C

Fig. 29



APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		

Fig. 30 prior art

